Halon Replacement



FK-5-1-12 Fire Extinction Behavior Below Room Temperature in a Forced Flow

Presented to: Seventh Triennial International Fire & Cabin Safety Research Conference

By: Doug Ingerson, Testing Engineer

Date: 5 December 2013

Presentation Overview

- Purpose & Basis
- Test Article Description

...test article, fire extinguishing system, telemetry

- Test Conditions
 - ...global test conditions
- Test Results
 - ...average values, observations, outcomes

Use of trade and/or manufacturer product names or services does not constitute endorsement.




Purpose & Basis

- To investigate the <u>fire extinguishment</u> behavior of FK-5-1-12 in a forced flow at :
 - full-scale
 - less than room temperature
 - "cool" ventilation
 - "cold"/"cool" boundaries
 - "cold"/"cool" FK-5-1-12
- The basis...
 - FK-5-1-12 & halon 1301 are notably different
 - A witnessed temperature-associated phenomena...



Purpose & Basis



Federal Aviation

Administration

Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Purpose & Basis

A witnessed phenomena (2006)...

- Test configuration & conditions
- Behaviors & observations

Purpose & Basis

Configuration & conditions

vaporous FK-5-1-12 & dry air mixture

measured at ≈11%v/v

- 2 copper sample lines
- 3.66 m x 3.18 mm OD
- drawn flow (suction) through each ≈800 sccm

atmosphere dry air source no more than 6 ppm H2O clear Tedlar 40L bag concentration unknown: SELECTOR VALVE LINE LENGTHS & WALL TEMPERATURES

• 3.05 m @ -16° < T_wall < -3°C

- 1.83 m, 4° < T wall < 8°C
- 2.53 m, 40° < T wall < 68°C

ch12 ch09

FAA-owned. MSSI/Pacific Scientific Halonyzer II Sensors



ch = channel, as in a channel number MSSI = Meggitt Safety Systems Inc.

Federal Aviation Administration


OD = outside diameter T_wall = wall temperature of copper sample line

Purpose

Comparing channel 12 behaviors...

...all looks reasonable...

...concentration calculated at 11.2% v/v




Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Federal Aviation

Administration

Purpose



Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Federal Aviation


Administration


Details of the full-scale testing (2011)


- Nacelle fire simulator (NFS) global orientation
- Making things "cold"
- Test telemetry package




The complete NFS







spray



- CONCENTRIC CORE & SHELL, 0.61 m (2 ft) OD CORE, 1.2 m (4 ft) OD SHELL
- 11 SAMPLE POINTS IN "FREE" STREAM (roughly 0.15 m off core sfc)
- 12TH SAMPLE POINT IS IN THE WAKE REGION OF THE FUEL PAN FWD LIP
- "PROTECTED" VOLUME ≈ 0.61 m LONG x 0.61 m ID x 1.2 m OD


"HOT" SFC IGNITION SOURCE


FUEL PAN -

FUEL SPRAY NOZZLES

CORE

SAMPLE POINT (typical)





sta 514 sta 502 sta 490 (12 in) FWD = forward


Federal Aviation

Administration

Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

SFC = surface

14





sta502


NFS doors with compartments

Making things "cold", the FK-5-1-12...

dry <u>ice</u> (solid carbon dioxide)


MSSI/Pacific Scientific fire extinguisher bottle and valve assemblies containing FK-5-1-12 & nitrogen gas





Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013





SURFACE-MOUNTED

THERMOCOUPLE

(frx btl shell)

NFS telemetry, if the extinguisher temperature & pressure

PLUMBING ASSEMBLY USED TO SENSE INTERNAL TEMPERATURE & PRESSURE



TAP FOR PRESSURE TRANSDUCER

THERMOCOUPLE TIP for internal temperature measurement (frx btl interior)


PRESSURE

TRANSDUCER

NFS telemetry, global view, optics & anemometry, spray fire region

sta502 core rib

ta477 core rib




Anemometer seeing

flow at 06:00. sta477

forward face of fuel pan


NFS telemetry, optics & anemometry,



fuel spray nozzles Anemometer seeing flow at 12:00, sta477

Test Article Description

NFS sta502 core rib telemetry, global view, optics & anemometry, pool fire region





optical path length approximately 0.3 m penetrating through "free"-stream flow

Test Article Description

LASER

NFS telemetry, optics & anemometry, pool fire region





Test Conditions

General global conditions

- NFS air mass flow ≈ 1.4 kg/s @ 1 atm, T≈8° or 47°C
- injected FK-5-1-12 masses of 4.3 or 6.4 kg

Limited comparative review accomplished here

- 13 total tests completed
- 8 tests reviewed here to assess FK-5-1-12 behavior
 - 6 tests related to a spray fire
 - 4 tests usefully group; tied to the lineage of the pool fire testing
 - 2 other tests usefully group; of their own lineage
 - 2 tests related to a pool fire




Test Conditions agent distribution fire extinguishment pres20131205.xls NFS TEST CONDITIONS == ventilation rate ----high low stream "temperature" ----ambient external wall "temperature" --ambient cold fire threat ----pool none FIREX SYSTEM DETAILS = FK-5-1-12 nitrogen "mass" injected ----largest smallest not determined storage "temperature" ----ambient cold storage "pressure" ----largest smallest injection configuration ----nozzle type "A" nozzle type "B" reviewed FIRE EXTINGUISHED === within yes (reignited) n/a T# 03 11317-15 T# 04 11321-16 T# 06 11329-12 T# 13 11401-13 T# 07 11329-14 T# 09 11330-12 T#11 11331-12 T# 08 11330-11 T# 12 11401-12 T# 05 11322-11 T#10 11331-11 T# 01




Test Results (graphical & tabular data)

Looking at select tests

- illustrating some behaviors
 - FK-5-1-12 distribution in the flow when all "hot"/ambient
 - injection plume insults on the environment :
 - thermally via type-K thermocouples
 - flow speeds via hot-wire anemometry
 - aerosol existence via light obscuration
- explaining the bases of calculated single-point values
- collectively review these values for global comparisons



Test Results (thermal graphs)



Federal Aviation

Administration

Test Results (thermal graphs) Thermal Behaviors, "cold", Air Stream & Other NFS Surfaces, Test #06/11329-12 (spray fire, typical) sta000, air/NFS inlet sta453, ave, air/NFS sta458/01:30, sfc/door, ext sta453, min/max, air/NFS sta514/11:30, sfc/door, ext sta470/06:00, sfc/core, ext sta546/01:30, sfc/door, ext sta483/12:00, sfc/core, ext frx btl shell frx btl interior **Temperature** thermal excursions indicate existence of and proximity to **Temperature** the spray fire (typical) **V**



Time (sec)

-15

-30

-45

-60 -75




-22


-49 -76

-103

Test Results (thermal graphs)



Test Results (thermal graphs)



Federal Aviation

Administration

Test Results (thermal descriptors)


Average Ambient Air (NFS Inlet), NFS
Ventilation Air, & FK-5-1-12
Temperatures
(T_{air}, T_{NFS}, T_{agent})

all are averages of the first 20 seconds in the test

T_{air} = ambient air temperature (NFS inlet), average of NFS inlet thermocouple signal

T_{NFS} = NFS ventilation stream temperature, average of the eight sta453 thermocouple signals

T_{agent} = FK-5-1-12 temperature, average of thermocouple signal for either the interior <u>or</u> the shell of the fire extinguisher bottle





Test Results (thermal graphs) Thermal Behaviors, "cool", sta445/left, ave - sta445/left, min/max NFS Doors, Interior Surfaces, sta445/right, min/max sta445/right, ave Test #09/11330-12 sta471/right, ave sta471/right, min/max sta494/left, ave sta494/left, min/max sta494/right, ave sta494/right, min/max increasing thermal excursions indicate existence of and proximity to fire **Temperature Temperature** (typical) decreasing thermal excursions indicate existence of and proximity to firex agent injection (typical) -15 -30-22 -45 -49 Time (sec) -76 -60 -75 -103



review slide 18 for telemetry details

Federal Aviation

Administration

Test Results (thermal graphs) Thermal Behaviors, "hot", sta445/left, ave -sta445/left, min/max NFS Doors, Interior Surfaces, sta445/right, min/max sta445/right, ave Test #05/11322-11 (typical) sta471/right, ave sta471/right, min/max sta494/left, ave sta494/left, min/max sta494/right, ave sta494/right, min/max **Temperature Temperature** -15 -30 -22 -45 -49 Time (sec) -76 -60 -75 -103




Test Results (thermal graphs) Thermal Behaviors, "cold", sta445/left, ave sta445/left, min/max NFS Doors, Interior Surfaces, sta445/right, min/max sta445/right, ave Test #06/11329-12 (typical) sta471/right, ave sta471/right, min/max sta494/left, min/max sta494/left, ave sta494/right, ave sta494/right, min/max Temperature **Temperature** -15 -30 -22 -45 -49 Time (sec) -60 -76 -75 -103



Test Results (thermal descriptors)


Average NFS Shell Temperature (T_{shell})

T_{shell} = average of sta445, 471, & 494 thermocouple signals in the first 20 seconds of the test




Federal Aviation

Administration




Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013


Federal Aviation




Federal Aviation




Federal Aviation




Federal Aviation



Federal Aviation



Federal Aviation




Test Results (thermal descriptors)


Temperature Ratio, sta551 (K_{j sta551})

(for each average temperature history of j = the lower or upper 6 sta551 thermocouples)

$$K_{j \text{ sta551}} = (T_{XTRM} - T_{NFS}) / (T_1 - T_{NFS})$$

- duration is the same & its location adjusted according to the FK-5-1-12 injection initiation signal
- with fire extinction,
 - √ T_{XTRM} ≈ T_{NFS}
 - $✓ K_{i \text{ sta551}} = 0$
- without fire extinction,
 - ✓ T_{XTRM} > T_{NFS}
 - ✓ if $0 < K_{j \text{ sta551}} < 1$, fire diminishing
 - ✓ if K_{i sta551} ≈ 1, fire unaffected
 - ✓ if K_{j sta551} > 1, fire relocating and/or intensity increasing; improved fuel/air mixing resulting from agitation by fire extinguishing agent injection plume; agent is not defeating the fire as fast as the fire is burning






Administration


Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Specific Heats (T=25°C, 1 atm)				
	C_P			
Substance	(kJ/(kg K))			
FK-5-1-12, liquid	1.103			
FK-5-1-12, vapor	0.891			
air	1.003			
water vapor	1.8723			
water	4.184			

- Hot-wire anemometry trends are interesting
- Limitations apply to the flow speed indications
 - anemometer calibration : dry air, 1 atm, 25° & 40°C
 - NFS ventilation stream differs from calibration basis :
 - atmospheric moisture present ≠ dry air
 - most flow temperatures ≠ 25°C
 - anemometers exposed to migrating FK-5-1-12 pulse in the ventilation stream; heat capacity of gas flow changes
 - H₂O & FK-5-1-12 existence is multi-phased (vapor, liquid, solid)
 - indications likely reasonable before FK-5-1-12 migration


2-5 December 2013





Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Federal Aviation



Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Test Results (anemometry graphs) 10 11330-11, sta477/12:00,axial -11330-11, sta477/12:00,rttnl -11330-11, sta477/06:00,axial 9 8 test 08 (large FK-5-1-12 mass) "cool" ventilation "cold" NFS doors "cold" FK-5-1-12 6 Flow Speed spray fire

90

95

100

Federal Aviation

Administration



Time (sec)

5

4

3


0


NFS Ventilation

Test Results (anemometry graphs) 10 11330-12, sta477/12:00,axial -11330-12, sta477/12:00,rttnl -11330-12, sta477/06:00,axial 9 8 test 09 (large FK-5-1-12 mass) "cool" ventilation ("cool") ambient NFS doors "cold" FK-5-1-12 6 Flow Speed spray fire 5 **NFS Ventilation** 4 3 Time (sec) 0 70 75 80 85 90 95 100

Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013








Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013

Federal Aviation

Test Results (anemometry descriptors)



(for each anemometer history at j = 12:00 or 06:00 & k = axial or rotational flow orientation)

x'ik: average flow speed

15 sec duration, before FK-5-1-12 injection (pre-injection)

A, area under flow speed curves

ik prini: 15 sec duration, pre-injection

 $A_{jk prinj} = 15 \text{ sec } * x'_{j}$ jk mig : 15 sec duration, includes

FK-5-1-12 migration (migration)


15 sec duration, rotating flow


15 sec duration, axial flow

Area Ratios

A_{jk mig} / A_{jk prinj} used to differentiate magnitudes & durations of the flow speeds during pre-injection & migration, at the same location

A_{jθ mig} / A_{jL mig} used to differentiate magnitudes & durations of the flow speeds during migration for rotating & axial directions, at the same location








Test Results (optics graphs)


- Light obscuration (L/O) is significant indicator
- Can <u>not</u> make simple calculations to characterize the FK-5-1-12 aerosol
 - FK-5-1-12 absorption/scattering properties?
 - "cold" FK-5-1-12 injection reduced local temperatures below water dew point in the moist-air ventilation stream; did a water aerosol (fog) form? yes...
 - while pre-test, hoar frost coated NFS door interiors; did frost suspend in the air flow with injection? yes...
- Timelines in L/O graphs are artificially aligned






Federal Aviation

Test Results (optics graphs)



Federal Aviation

Test Results (optics graphs)



Seventh Triennial International Fire & Cabin Safety Research Conference Philadelphia, PA, USA 2-5 December 2013


Federal Aviation

Test Results (optics descriptor)



$$% I_{OBS} = 100 * area A$$
(area A + area B)

- At 100% light transmission (I₁₀₀), optical receiver signal = maximum voltage
- At 100% light obscuration (I₀), optical receiver signal = 0 volts
- $I(t) = \underline{\text{instantaneous voltage}}$ [average voltage at I_{100} for Δt_6]



 $\Delta t_{20} = 20 \text{ sec}$

starting time of obvious

signal loss

Federal Aviation

Test Results (tabular summary) 10 12 13 08 07 09 test date & run # 11322-11 11329-12 11329-14 11331-11 11401-12 11401-13 11330-11 11330-13 fire ext, fire ext, fire ext, fire ext, fire ext, fire ext, agent fire ext, Type of test distribution spray fire spray fire spray fire pool fire pool fire spray fire spray fire Did the fire extingiush (assessed by visual inspection)? no yes/reignited **Temperature Indications** air/KACY (°C) 13 11 5 3 H2O dew point in air/KACY (°C -11 -10 3 -5 -1 air/NFS inlet (°C) 17 11 5 4 air/NFS sta453 average (°C 47 12 9 7 9 -54 38 14 14 FK-5-1-12 (°C) shell/average of interior NFS door surfaces, sta 445, 471, & 494 (°C 37 13 50 upper sta551 average, pre-injection (°C' 713 702 717 45 42 719 718 lower sta551 average, pre-injection (°C) 45 33 36 37 115 113 34 38 difference, upper sta551, deviation due to injection (°C -49 -73 -205 +180+117-74 -79 difference, lower sta551, deviation due to injection (°C +25 +30+45 +114+111+18+15temperature ratio, upper sta 551 0.93 0.89 0.71 5.5 4.08 0.9 0.89 2.04 temperature ratio, lower sta 551 1.96 2.02 1.67 1.48 **Anemometry Indications** average speeds, pre-injection sta477, 12:00 axial (m/s) 2.3 2.2 2.2 2.3 2 2 2.1 2.2 sta477, 12:00 rotational (m/s) 0.8 0.8 0.9 0.8 0.6 0.6 sta477, 06:00 axial (m/s 2.1 2 2.1 2.2 2.2 2.1 2.2 sta477, 06:00 rotational (m/s) 0.4 0.4 ratio, areas under flow speed curves (FK-5-1-12 migration) / (pre-injection) sta477, 12:00 axia 1.7 1.5 1.1 1.1 1.6 1.2 1.2 sta477, 12:00 rotational 5.2 4.9 4.8 5 12.9 7 sta477, 06:00 axia 0.9 1.3 1.3 0.9 0.9 sta477, 06:00 rotationa 7.5 7.7

4.5

4.39

4.8

4.73

Changes in Light Obscuration from Test to Test (for select test pairs)								
Proportional change		Percent change in light obscuration						
in light obscuration	(positive number signifies increasing obscuration)							
Test #5 to #6 (#6 / #5)	10.452	Test #5 to #6 ([#6 - #5] / #5)	945.2					
Test #6 to #7 (#7 / #6)	1.077	Test #6 to #7 ([#7 - #6] / #6)	7.7					
Test #7 to #12 (#12 / #7)	5.416	Test #7 to #12 ([#12 - #7] / #7)	441.6					
Test #7 to #8 (#8 / #7)	3.573	Test #7 to #8 ([#8 - #7] / #7)	257.3					
Test #12 to #13 (#13 / #12)	0.756	Test #12 to #13 ([#13 - #12] / #12)	-24.4					
Test #8 to #9 (#8 / #9)	0.692	Test #8 to #9 ([#9 - #8] / #8)	-30.8					

12:00

06:00

sta473, 12:00 axia

sta473, 06:00 axial

3.5

0.42



10.8

16.9

5.8

11.7

ratios, areas under flow speed curves, FK-5-1-12 migration (rotational / axial)

5.8

25.62

5.9

19.38

4.5

sensing failed

Percent Light Obscuration Indications

Fire extinguishment not observed

- notable behavior occurred 1X against a pool fire (13)
- fire pushed from pool, but regained it (not extinguished)
- why this behavior?
 - pool combustion not as thermally effective as spray combustion
 - "large"- versus "small"-surface fuel diffusion; spray versus pool;
 with increasing diffusion, combustion likely improves
 - steady global conditions more critical to pool fire stability
 - loss of liquid FK-5-1-12 from ventilation stream
 - "protected" & flame volumes not concurrent
 - rate of local FK-5-1-12 transformation into useful state/form lacked compared to that of air & fuel in the combustion process



- "cold" condition observably affected FK-5-1-12 injection
 - compare tests {"hot" & no fire} / {"cold" & spray fire} (5/6)
 - reviewing L/O behaviors
 - L/O increased 0.4% / 4.4% (respectively); magnitudinally larger; +945%
 - FK-5-1-12 end-state <u>not</u> all vaporous in 6 (%L/O notably ≠ 0)
 - reviewing anemometry behaviors
 - 6's rotational/axial ratio fractionally larger; flows less alike than in 5
 - reduction in axial flows is notable & greater than that for rotation
 - larger reduction in axial flow indicating less migratory expansion
 - L/O is the basis for the statement; anemometry tentative, yet, trends lend support



- global "cold" FK-5-1-12 distribution behavior in the NFS
 - FK-5-1-12 favored NFS lower lobe, even with rotating injection
 - compare & blend {12:00 spray fire} / {06:00 pool fire} (7/12)
 - L/O increased 4.7% / 25.6%; multiply larger at 06:00; +442%
 - with larger L/O in lower lobe, more FK-5-1-12 resident
 - FK-5-1-12 injection plumes captured rotating around core
 - notable spike observed in L/O histories; 6-9 & 13; 2 spikes in 9?
 - spike separates 2 durations of more aerosol-laden flow
 - oscillating signal expected at fixed point subject to rotating plumes
 - plausible given injection plumbing created rotation during injection
 - spike & L/O excursion durations & proportionalities dissimilar;
 indicating some transition?



- outcome not significant for increasing FK-5-1-12 mass
 - review small/large injected masses (7/8); both "cold" FK-5-1-12
 - L/O increased from 4.7% to 16.9%; multiply larger; +253%
 - reviewing anemometry behaviors
 - indicates <u>significant</u> rotational flow in 8; a "wet" hot-wire ?
 - axial flow perturbations roughly 1-2 seconds longer in 8
 - <u>reviewing sta551</u> behaviors
 - comparable thermal excursions in upper lobe; -73° ≈ -74°C
 - observable decrease in lower lobe excursions
 - $* +30^{\circ}C > +18^{\circ}C$
 - » due to more "cold" FK-5-1-12, with minimal effect on fire?
 - thermal degradation faster during 7



- what affects FK-5-1-12 more? "cold" FK-5-1-12 or walls
 - confounding issues
 - optical history not captured for test 10 due to telemetry fault
 - pool fire test configuration (12/13) versus spray fire (8/9, 7/10)
 - 2 different FK-5-1-12 masses injected (8=9 > 7=10=12=13)
 - L/O suggests "cold" walls affected FK-5-1-12 more
 - compare "cold"/"cool" agent (12/13) & "cold"/"cool" walls (8/9)
 - L/O decreased 24% (12/13) & 31% (8/9)
 - » 12/13 : L/O decreased from 25.62 to 19.38% (7 at 4.7%)
 - » 8/9 : L/O decreased from 16.9 to 11.7%
 - larger change in aerosol quantity for "cold"/"cool" walls
 - pool/spray? 2 masses? large mass more fog? warm wall no frost?-



- what affects FK-5-1-12 more? "cold" FK-5-1-12 or walls
 - anemometry suggests "cold" walls affected FK-5-1-12 more
 - compare "cold"/"cool" FK-5-1-12 (7/10 & 12/13) against "cold"/"cool" walls (8/9)
 - NFS walls played an observable role
 - » isolate & look at each test pair for its behavioral change due to its conditional change, then compare the sizes of changes
 - 8/9 differ from others due to larger FK-5-1-12 injection
 - others differ from 12/13 due to anemometer location
 - » largest difference is that of rotational flow seen between 8/9; due to notable change in *rotational* flow behavior
 - largest change between tests in each test pair is for the rotational flow between 8/9



Thermal Excursions at sta551							
	sta551			Temperature			
	Sample		Condition of	Excursions			
Tests	Position	Variable	Variable	(°C)			
7/10	upper	FK-5-1-12	"cold"/"cool"	-73/-205			
	lower	(small mass)		+30/+45			
12/13	upper	FK-5-1-12	"cold"/"cool"	+180/+117			
	lower	(small mass)		+114/+111			
8/9	upper	NFS walls	"cold"/"cool"	-74/-79			
	lower	(large mass)		+18/+15			

- what affects FK-5-1-12 more? "cold" FK-5-1-12 or walls
 - consider temperature behaviors at NFS sta551
 - still comparing tests for varied FK-5-1-12/NFS wall temperatures...
 - (7/10), (12/13), & (8/9)
 - sta551 pre-injection values show fires behaved consistently
 - thermal excursions are largest for "cold"/"cool" FK-5-1-12
 - » largest decrease for "cool" FK-5-1-12/"cold" NFS walls (10)
 - » related excursions decrease or are similar for 12/13
 - » related excursions are similar for "cold"/"cool" NFS walls (8/9)
 - increasing FK-5-1-12 temperature better improved its ability



- what affects FK-5-1-12 more? "cold" FK-5-1-12 or walls
 - why a conflict in the means of observation/comparison?
 - L/O & anemometry suggest "cold" walls are more significant
 - sta551 trends suggests storage temperature is more significant
 - conflict relates to the question "...what affects FK-5-1-12 more..."
 - » affecting how? as defined by use for this application...
 - » state of FK-5-1-12 after injection? relates to migratory state; indicated by L/O & anemometry trends…
 - » FK-5-1-12 ability to extinguish fire? relates to fire extinction; indicated by sta551 trends…
 - does FK-5-1-12 mist/spray work like FK-5-1-12 vapor? based on that seen here, no...



Test Results (conclusions & considerations)

Concluding

- no fires were extinguished in 13 tests
- test 10 & 13 provided most interesting observations
- while maintaining the same injection plumbing...
 - storage & environmental temperatures notably affected the state
 & dispersion of FK-5-1-12
 - "cold" FK-5-1-12 settled low in the NFS (all tests run at similar air mass flow rate)
 - "cold" boundaries notably affected the injection plumes
 - increasing the "cold" mass negligibly changed fire suppression
 - increasing storage temperature improved fire suppression

Test Results (conclusions & considerations)

Considerations

- witnessed phenomena (slides 6-8) ≠ full-scale testing (slides 10-68)
 - witnessed phenomena: initially-"warm" vapor mass lost to boundary by condensation, at reduced temperature & pressure
 - full-scale testing: reduced boundary & FK-5-1-12 temperatures did not extinguish fire at atmospheric pressure
- substance trends moving to less-energetic materials
- with aerosol existence in a "protected" volume :
 - use of a Statham-derivative gas analyzer is questionable
 - does FAA A.C. 20-100⁽⁵⁾ concentration framework remain valid?
 - volumetric concentration?
 - ½ second residence time remain unchanged?



Recognition of Contributions by Others

Please recognize additional contributions to this body of work from the following individuals:

- Mr. Stephane Pugliese, Airbus Industries, Toulouse, France
- Mr. James Mavricos, Meggitt Safety Systems Incorporated, Duarte, CA, USA
- Mr. Dick Hill, Mr. Jason Fleming, Mr. Mark Materio, Mr. Tom Carmen, FAA
 Technical Center, Atlantic City International Airport, NJ, USA
- Mr. Stephen Happenny, FAA Northwest Mountain Region, Renton, WA, USA



Referable Information

- 1. Thermodynamic data provided by:
 - DuPont "Thermodynamic Properties DuPont Halon 1301 Fire Extinguishant," Bulletin T-1301, E.I. Du Pont De Nemours & Co, Inc, Wilmington, DE, USA, Feb, 1966.
 - · personal communication, Paul Rivers, 2006.
- 2. FK-5-1-12 & halon 1301 cup-burner & peak-inerting experimental concentrations
 - Hamins, et al., 1994, "Flame Suppression Effectiveness," NIST Special Publication 861, National Institute of Standards & Technology, Building and Fire Research Laboratory, Gaithersburg, MD.
 - National Fire Protection Association, 2007, "NFPA 2001 Standard on Clean Agent Fire Extinguishing Systems," 2008 Edition, Quincy, MA.
 - National Fire Protection Association, 1989, "NFPA 12A Standard on Halon 1301 Fire Extinguishing Systems," 1989
 Edition, Quincy, MA.
 - FK-5-1-12 cup-burner & peak inerting concentration values

cup-burner: NFPA, 2007, Tables A.5.4.2(a) & A.5.4.2(b), p.50.

peak inerting: NFPA, 2007, Table A.5.4.3, p.55.

halon 1301 cup-burner & peak inerting concentration values

cup-burner: Hamins, 1994, table 5, p.395.

peak inerting: NFPA, 1989, derived from table A-2-3.2.1, p.15.

3. Presentation on Outcomes from MPSe Revision 03 Testing, found at :

http://www.fire.tc.faa.gov/pdf/systems/Oct06Meeting/Ingerson-1006-HalonReplacement.pdf

- Working Copy of Draft MPSe Revision 04, found at http://www.fire.tc.faa.gov/pdf/systems/MPSErev04 MPSeRev04doc-02submtd.pdf
- 5. Advisory Circular 20-100, 1977, "General Guidelines for Measuring Fire-Extinguishing Agent Concentrations in Powerplant Compartments," United States Department of Transportation, Federal Aviation Administration, Washington, DC, http://rgl.faa.gov/Regulatory and Guidance Library/rgAdvisoryCircular.nsf/list/AC%2020-100/\$FILE/AC20-100.pdf

